

Key activities: Remediation works along Solander Street are being finalised. Rec Club carpark remedial works in progress. Replacement works of driveways of private property in Zone 1 are continuing. Works on the access path to the Girl Guide Hall is progressing.

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	Remediation of gross contamination has been completed. Validation results from this zone have been published. Apart from one location, remediation was successful. The impacted soil at this one location has been removed. Awaiting validation results. Watering of newly installed grass is continuing. Remaining works also include remediation works of driveways and in private properties. These works are being coordinated with individual residents.
2	Impacted area near horse arena	Remediation of gross contamination has been completed. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediation of gross contamination has been completed. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Remediation of gross contamination has been completed. Validation results from this zone published so far (~ 90%) show that remediation has been successful apart from one location. The impacted soil at this one location has been removed. Awaiting validation results for this one location. Other validation results that are outstanding will be published when available. Watering of newly installed grass continuing.
4 East	East side of Captain Cook Drive between Torres and Solander Streets.	Remediation of gross contamination has been completed. Validation results for 85% of this zone south from the roundabout have been published, showing that remediation was successful. Watering of newly installed grass and garden is continuing. Remaining works along Solander Street are being completed. The remaining works also include the access ramp to the Girl Guide Hall and the reinstatement of the embankment and railing along a section on the northern side of Solander Street.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	Remediation of gross contamination has been completed. Validation results from this zone have been published. Apart from two locations, remediation was successful. The impacted soils at these two locations have been removed. Awaiting validation results. Watering of newly installed grass is continuing.
5	Area behind Girl Guides Hall	Remediation of gross contamination has been completed. Validation results from this zone have been published, showing that remediation was successful. Watering of newly installed grass continuing.
6	Western side of Captain Cook Drive south of Bridges Street	Remediation of gross contamination has been completed. Validation results from this zone have been published. Apart from two locations, remediation was successful. The remaining impacted soil in one of these 2 locations has been removed. Awaiting validation results. Since the second location is among tree roots, a monitoring plan will be implemented involving an arborist. There are no risks from small amounts of remaining contaminants identified since the impacted soil is already covered with clean soil and fresh grass.

		Watering of newly installed grass is continuing. Remaining works include the development of a management plan for the remaining contamination that cannot be removed without causing further impact.
7	Area in front of Rec Club and southern side of Solander Street	The section along Captain Cook Drive (~70% of the zone) has been remediated or grass has been replaced. Awaiting validation results Remediation and grass replacement works will continue in this area and into the carpark of the Rec Club.
8	Impacted private property	Remediation of gross contamination has been completed. Validation results show remediation was successful.
<b>Clean-up</b>		
Waterways		Cleaning up in waterways is continuing.
<b>Other updates</b>	See <a href="https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update">https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update</a> - for further updates. We are working as quickly as possible to complete the remediation work. To ensure everyone's safety, please adhere to signage when driving or walking past the remediation work areas.	
<b>Contact Ampol</b>	Ampol Community Hotline <b>1800 719 669</b> or <a href="mailto:Community@ampol.com.au">Community@ampol.com.au</a>	