

Works progressing well, focusing along western side of Captain Cook Drive. Continued grass care on Sunday 8 May with limited work crew to minimise traffic disruption. Vehicle access to carpark in front of the shops will remain open with minor delays expected. Limiting as many safety cones and barricading around fresh turf as possible. Minimal work crews Sunday 8 May mainly doing watering of grass and monitoring creek and waterways

Remediation Zone	Location description	Work completed
1	Area north of Torres St/Captain Cook Drive roundabout	~75% remediated. This includes the grassed areas in the road verge. Awaiting validation results from remediation sections. Watering of newly installed grass. Remediation works of driveways and in private properties (remaining 25%) is being organised with the individual residents directly.
2	Impacted area near horse arena	Remediation 100% complete. Area has been reopened. Validation results have been published. Watering of newly installed grass.
3 West	Area southwest of Torres St / Captain Cook Drive roundabout	Remediated and covered with turf. Await validation resampling results. Watering of newly installed grass.
3 East	Area southeast of Torres St / Captain Cook Drive roundabout	Watering of newly installed grass of remediated section. ~25% of the zone has been remediated. Awaiting validation results of that section. Remaining area is scheduled for remediation early in the week.
4 East	East side of Captain Cook Drive between Bridges and Torres Streets	~ 70% of the zone has been remediated. Awaiting validation results of that section. Watering of newly installed grass.
4 West	West side of Captain Cook Drive between Bridges and Torres Streets	The garden at “the meeting place” sign has been remediated and is ready for mulch and plants to be reinstated. Area on the corner of Captain Cook Drive and Bridges Street and into Bridges Street has been remediated. ~70% of the Zone has been remediated. Awaiting validation results of that section. Watering of newly installed grass continuing. Crew working west along footpath along north side of Bridges Street.
5	Area behind Girl Guides Hall	Remediation completed of the central section of this Zone. Awaiting validation results of that section. Crew to focus on remediating affected areas further east behind girl guides hall early in the week. Watering of newly installed grass continuing.
6	Western side of Captain Cook Drive south of Bridges Street	Work crew continued remediation around the footbridge. Turf laid in the remediated section at bridge to enable safe pedestrian access from Tasman Street bridge to bus stop. ~75% of the Zone has been remediated. Awaiting validation results of completed sections. Watering of newly installed grass continuing.
7	Area in front of Rec Club and southern side of Solander Street	Works have not yet commenced in this area.
8	Impacted private property	Works have not yet commenced in this area. Awaiting owners’ approval.
Clean-up		
Waterways		Cleaning up in waterways is continuing.
Other updates	See https://www.ampol.com.au/about-ampol/news-and-media/kurnell-update . Results from Balboa Street have been posted.	
Contact Ampol	PLEASE NOTE NEW PHONE NUMBER AND EMAIL ADDRESS Ampol Community Hotline 1800 719 669 or Community@ampol.com.au	